

# **Transmitter for temperature**, head mounting for Pt 100, selectable measuring ranges, Type series PA2240



# Features

- Suitable for mounting in connection heads per DIN 43729
- Connection Pt 100, 3-wire circuitry
- Measuring range selectable via solder pads
- Output signal: 4...20 mA, 2-wire circuitry, temperature linear
- Adjustable Pt 100 sensor break alarm
- Power supply: 6.5...32 V DC
- Large ambient temperature range
- Compact low profile for easy installations

# Application

The transmitter for Pt 100 converts a temperature dependent change of resistance into a standard load-independent current signal of the type commonly used in process control systems. It is designed for mounting in the connection head model B, DIN 43729. Measuring ranges are adjusted easily with solder pads.

# · Chemicals/petrochemicals

**Application area** 

· Maschinen- und Anlagenbau

· Food/phamaceuticals/biotechnology

# Techn. Data

#### Mechanical design

housing material zinc alloy and ABS/VO protection: housing with cover IP 20 terminals IP 10

#### Mounting

screw holes for in-head mounting according to DIN B-head or larger

# Connections

terminal screws for wire or flexible lead  $\leq 2.5 \text{ mm}^2$ 

# Housing temperature

operation: -40...+85 °C storage: -40...+100 °C

#### Auxiliary energy supply

connection polarity safe function range: 6.5...32 V DC residual ripple 4 V<sub>ss</sub> at 50/60 Hz

#### EMC

noise immunity as per EN 50082, section 2 emitted interference as per EN 50081, section 2

# Influence of the supply voltage on the output signal

 $\pm$  0.02 % of span/V supply ripple influence, 50/60 Hz, 4 V $_{\rm SS}$ :  $\pm$  0.05 % of span

# Signal input

Pt 100, 3-wire circuitry. 2-wire connection possible with wire jumper. The wire jumper has to be connected during installation. Sensor feed I approx. 1.1 mA max. sensor wire resistance: 15 Ohm/wire terminal assignment as per connection diagram

#### Measuring ranges

adjustable according to table "Zero point configuration" Zero point between -50...+50 °C

## Measuring spans see page 3, ± 10 % changeable

Output signal temperature linear 4...20 mA

#### Break alarm

if the Pt 100 sensor is fractured, the output signal optionally takes values approx. 25 mA or approx. 3 mA

Current limitation in output signal max. output current approx. 25 mA

#### Load

for U = 24 V DC, 25 mA R = 700 Ohm

Load diagram see page 2

Linearity error ± 0.1 % of span

**Temperature influence** ± 0.6 % of span/25 °C

Adjusting range

zero point: between -50...+50 °C measuring span:  $\pm$  10 % f.s.

Weight approx. 40 g

# Load diagram



supply voltage VDC





Connections

supply voltage

Note: Connect a wire jumper from terminal 1 to 3 for a 2-wire connection. The line resistance of the sensor will thus be included as a measuring error in the measurement.

# Mounting and operating insructions

# Installation

Always use the cover when the transmitter is not in the configuration phase. The cover prevents the transmitter from getting dirt on the soldering pads as well as getting ESD (Electro Static Discharge) by accidental touch of the soldering pads.

dimensions in mm

A convenient way to install the transmitter is to use the mounting kit.

In order to minimize measuring errors make sure the connecting screws are tightened enough.

# **General information**

It is suggested that the calibration is checked at least once a year. Recommended calibration equipment is a resistance source and a mA-meter. For a calibration accuracy of 0.1 % we recommend calibration instruments with an accuracy of at least 0.02 %. The transmitter is polarity protected and will not be damaged by connecting the power supply with the wrong polarity, but the output will be 0 mA. The maximum load in the output loop depends on the supply voltage (see load diagram). As all transmitters with potentiometer adjustments, this transmitter must not be exposed to heavy shocks or vibrations which may cause the transmitter to get out of calibration.

To avoid ESD (Electro Static Discharge) to the transmitter, which may cause permanent damage, always ground yourself by touching some grounded equipment before configuring the transmitter.

# Configuration

(To be carried out before calibration)

Setting is done with solder jumpers. These are 9 positions and each position consists of 3 solder pads (see figure).

- 1. Select zero point according to figure. The solder jumper for position 9 is given for each interval in the figure.
- 2. Select span according to the table.
- 3. Select burn-out detection according to table.
- 4. Carry out the soldering of the jumpers according to tables.

# Calibration

(To be carried out after configuration)

- 1. Connect the transmitter to a supply voltage, wire the terminals according to the wiring diagram and replace the Pt 100 with a precision decade resistor.
- Apply an input signal to give an output of approximately 12 mA and leave the unit for 15 minutes, if possible in the ambient temperature it is intended to work in.
- 3. Apply INmin corresponding to desired minimum input signal, e.g. 0°C at Pt100 = 100.00 Ohm.
- 4. Adjust the Z-potentiometer to get lout = 4.00 mA.
- 5. Apply INmax corresponding to desired maximum input signal.
- 6. Adjust the S-potentiometer to get lout = 20.00 mA
- 7. Repeat 3-6 until readings converge.
- 8. Secure the potentiometer with lacquer.
- 9. Calibration is completed.

# Dimensions



Position of the connection terminals, solder pads, potentiometers and a configuration example: meas. range: 0...100 °C sensor break signal:>23 mA

# adjustment of measuring ranges °C



# Zero point configuration meas. span °C



solder pad field 9

# Sensor break configuration



# Order Details

- please give additional specifications for models not listed -

Transmitter for temperature		PA2240	]	
meas. range	without configuration		F11001	
meas. range adjusted at factory	-5050 °C		F12160	
	-1040 °C		F12345	1
	050 °C		F12420	
	0100 °C		F12426	]
	0150 °C		F12430	1
	0200 °C		F12434	
	0300 °C		F12438	1
	0400 °C		F12440	1
	0500 °C		F12441	1
	per customer choice		F12999	
break alarm	without configuration			<b>K1</b>
	· signal approx. 25 mA, standard <sup>1</sup>			K2
	· signal approx. 3 mA 1			K3
		•	•	-
Order code (example):		PA2240	F12426	K2

<sup>1</sup> configured only when measuring range is adjusted at factory, otherwise not configured